





F100	M	ISO 2568	6g	1.75XP	HSS		
F201	M	ISO 2568	6g	1.75XP	HSS		
F108	M	ISO 2568	6g	2.25XP	HSS-E		

L120  
309

- F100** • M Gängsnitt, Spåndrivande Skär
- F201** • M Kierleuat, lastua työntävä kärki
- F108** • M Gjengesnitt, Spondrivende Skjær
- F108** • M Gevindbakker, Spåndrivende Skær

F100; F201	■	1.1	1.2	1.3	3.1	3.2	3.3	7.1	7.2	7.3											
	■	1.4	2.1	2.2	3.4	4.3	5.1	5.2	5.3	6.1	6.2	6.3	7.4	8.1	8.2	8.3					
F108	■	1.3	1.4	2.1	2.2	3.1	3.2	3.3	7.1	7.2	7.3										
	■	1.1	1.2	1.5	2.3	3.4	4.1	4.3	5.1	5.2	5.3	6.1	6.2	6.3	6.4	7.4	8.1	8.2	8.3		



F100	F201	F108
		
M2 - M42	M3 - M20	M2 - M20

M	P mm	d <sub>2</sub> Ø mm	h <sub>1</sub> mm	F100	F201	F108
2	0.40	16	5	F100M2		F108M2
2.5	0.45	16	5	F100M2.5		F108M2.5
2.6	0.45	16	5	F100M2.6		
3	0.50	20	5	F100M3	F201M3	F108M3
3.5	0.60	20	5	F100M3.5		
4	0.70	20	5	F100M4	F201M4	F108M4
4.5	0.75	20	7	F100M4.5		
5	0.80	20	7	F100M5	F201M5	F108M5
6	1.00	20	7	F100M6	F201M6	F108M6
7	1.00	25	9	F100M7		
8	1.25	25	9	F100M8	F201M8	F108M8
9	1.25	25	9	F100M9		
10	1.50	30	11	F100M10	F201M10	F108M10
11	1.50	30	11	F100M11		
12	1.75	38	14	F100M12	F201M12	F108M12
14	2.00	38	14	F100M14	F201M14	F108M14
16	2.00	45	18	F100M16	F201M16	F108M16
18	2.50	45	18	F100M18	F201M18	F108M18
20	2.50	45	18	F100M20	F201M20	F108M20
22	2.50	55	22	F100M22		
24	3.00	55	22	F100M24		
27	3.00	65	25	F100M27		
30	3.50	65	25	F100M30		

<sup>1)</sup> Ej spåndrivande skär / Ei lastua työntävä kärki / Ikke spondrivende skjær / Ikke spåndrivende skjær

M	P mm	d <sub>2</sub> Ø mm	h <sub>1</sub> mm	F100	F201	F108
33	3.50	65	25	F100M33		
36	4.00	65	25	F100M36		
39	4.00	75	30	F100M39		
42	4.50	75	30	F100M42		